
OTHERS JUST CAN'T COMPETE





35%

less oil passing than the competition




*Higher levels of oil passing may cause downstream contamination and total failure.

Don't get burned by inferior parts. Only genuine Bendix reman BA-921 HDEP compressors are:

- Remanufactured to OE clearances and specifications
- Tested to the highest standard using proprietary test specifications
- Expertly remanufactured to outlast any competitor



Stay on the road and out of the service bay with genuine Bendix® remanufactured compressors.



Visual representation only. Not to scale and not intended to illustrate actual clearances.

Bendix rebores the crankcase and matches the piston to maintain OE clearances each time a compressor is remanufactured.

Not maintaining the OE piston to crankcase clearances may cause a higher volume of oil passing, increasing the risk of down stream contamination and component failure.



Non-Genuine Rebuilt BA-921 HDEP Compressor

Built to Compete. Remanufactured to last.

Contact your Bendix account representative to learn more about the genuine Bendix BA-921 HDEP remanufactured compressor today.



