Part Number Update

Bulletin No: PNU-197 Effective Date: August 12, 2014 Cancels: NA Page: 1 of 2

Subject: Bendix Announces Forward Looking Radar (FLR) Sensor Reman Kit Part Numbers for Mack® Vehicles

Effective immediately, Bendix announces that remanufactured Bendix™ FLR20™ radar sensors will be used as a replacement for Mack® vehicles originally equipped with Bendix™ FLR10™ radar sensors. See below for the available kits. Please note that these kits must be ordered from Mack dealers.

Kits include the bracket and components needed to perform the installation, however an alignment tool and digital inclinometer will also be required to complete the installation and alignment.



Bendix FLR10 Radar Sensors	Mack Replacement Kit Numbers
(Bendix Core Group SG, Core Class F6)	(Bendix Core Group SH, Core Class F8)
K035749	Order 85143481 from your Mack dealer
K036727	
K040234	
K043283	
K046886	
K051105	
K051511	
K056476	
K056478	
K070393	







Note: Return Bendix FLR10 radar sensors for Core credit.


CORE EXCHANGES

Since the Bendix[™] FLR20[™] radar sensor replaces a Bendix[™] FLR10[™] radar sensor, when customers return the part for Core credit it is important to use a BW1829 orange tag. This will alert the Bendix Receiving Plant that the Core is eligible to be applied to the Bendix FLR20 radar sensor Core group.

For more information about the change detailed in this document, please contact your Bendix Account Manager at 1-800-AIR-BRAKE (1-800-247-2725).

Reference Document:

For more information about the radar sensor (including the alignment procedure), see the Bendix Wingman Advanced (FLR20 sensor) Service Data Sheet: SD-61-4960. This document is available for download from the Bendix Document Library at www.bendix.com, or may be ordered from the Online Marketing Center.



Cancels: NA

Log-on and Learn from the Best

On-line training that's available when you are -24/7/365. Visit www.brake-school.com.

